

# General Environmental Incident Summary

**Incident:** 4134      **Date/Time Notice:** 6/16/2016      **DEM Incident No:**  
**Responsible Party:** Sterling Construction Management, LLC  
**Date Incident:** 6/14/2016      **Time Incident:** 1600      **Duration:**  
**County:** Dunn      **Twp:** 148      **Rng:** 97      **Sec:** 35      **Qtr:**  
**Lat:** 47.58937      **Long:** -103.00310      **Method:** Navigation quality GPS  
**Location Description:** Bear Creek NGL Pipeline, Spread 2 ROW STA 1048+00 (killdeer nearest town)

**Submitted By:** Chase Edmiston      **Affiliation:**  
**Address:** 100 West Fifth Street  
**City:** Tulsa      **State:** OK      **Zip:** 74103

**Received By:**

**Contact Person:**

10020 HWY 200 East  
Dunn Center, ND

**Distance Nearest Occupied Building:**      **Release Contained:** Yes

**Type of Incident:** Equipment Failure

**Description of Released Contaminant:** Drilling Mud (Water and Bentonite)

**Volume Spilled:** 50.00 gallons      **Ag Related:** No

**EPA Extremely Hazardous Substance:** Unknown      **Reported to NRC:** Unknown

**Cause of Incident:**

Inadvertant release during HDD.

**Risk Evaluation:**

None

**# of Fatalities:**      **# of Injuries:**      **Affected Medium:** 03 - soil

**Potential Environmental Impacts:**

Localized area of soil affected. Occured in upland area and no sensitive resources were affected.

**Action Taken or Planned:**

The spill was contained using silt fence. The mud was cleaned up using a vac truck and spread in designated area on ROW.

**Wastes Disposal Location:**

**Agencies Involved:**

## ***Updates***

---

***Date:*** 6/16/2016    ***Status:*** No Further Action Requested

***Author:*** Souder, Taylor

***Updated Volume:***

***Notes:***

According to the report, there was a release of drilling mud from pipeline installation. No further follow-up needed.